

Delete
machine
guard and
redundant
spindle

Shrink mill - Max height of
mill should be red line,
preferably not interfering
with the forging **arm**.

“Square-off” / finish the base of the
mill so it’s appears that it is sitting flat
on the platform.

Drill bit and flying chips

