




This is a background component, not an active drilling part

This part needs to go away

Proposed cutting path (parallel to left side of platform 90 deg turn, then parallel to front edge of platform)

The mill bit should be in the yellow box. This bit should contact the platform. (This means the whole mill can be lowered about 25%)



Try to have the cutting trail not blend in with the mill base.